Printed on: 8/30/2009 8:03:48 PM

National Transportation Safety Board	NTSE	ID: ERA09WA2	91	Aircraft Regist	Aircraft Registration Number: N502TC			
FACTUAL REPORT		rrence Date: 05/10	0/2009	Most Critical In	Most Critical Injury: Fatal			
AVIATION	Occui	rence Type: Accid	dent	Investigated B	Investigated By: Foreign			
Location/Time								
Nearest City/Place	State	Zip Code	Code Local Time					
Port Sudan			0530	UTC				
Airport Proximity: Off Airport/Airstrip	m Landing Facility:	anding Facility:						
Aircraft Information Summary								
Aircraft Manufacturer		Model/Serie	S			Type of Aircraft		
PIPER	PA-30			Airplane				
Revenue Sightseeing Flight: No	Air I	Air Medical Transport Flight: No						

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On May 10, 2009, at 0530 universal coordinated time (0830 local time), a Piper PA-30, N502TC, was destroyed when it impacted mountainous terrain about 26 nautical miles northwest of Port Sudan, Sudan. The two Yemani pilots onboard were fatally injured. The airplane was operating on an international flight plan between Luxor International Airport (HELX), Luxor, Egypt, and Port Sudan New International Airport (HSPN), Port Sudan, Sudan, under Sudanese flight regulations.

The investigation is under the jurisdiction of the Republic of Sudan. Further information may be obtained from:

Civil Aviation Authority Air Accident Investigation Directorate P.O. Box 430 Republic of Sudan

Tel: 249 155775152 Fax: 249 155775150

This report is for informational purposes, and only contains information released by the Republic of Sudan.

Updated on May 26 2009 12:30PM

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ERA09WA291

Occurrence Date: 05/10/2009

AVIATION	Occurre	nce Type:	Accident								
Landing Facility/Approach In	formation										
Airport Name		Air	port ID:	Airport Elevation	Run	way Used	Runwa	ay Length		unway Width	
				Ft. MSL	_ N/A	A					
Runway Surface Type:					•		•		,		
Runway Surface Condition:											
	_										
Approach/Arrival Flown: NONE	=										
VFR Approach/Landing: Unknown	1										
Aircraft Information			Model/	Carias				Sorial	Number		
Aircraft Manufacturer PIPER			PA-30					30-88			
Airworthiness Certificate(s): Norm	al		<u> </u>					<u> </u>			
Landing Gear Type: Retractable	- Tricycle		Т								
Amateur Built Acft? No		d Max Gross Wt.		LBS	Numbe	r of Engi					
				Engine Manufacturer: Model/Series: LYCOMING IO-320 SERI						tated Power: 150 HP	
- Aircraft Inspection Information		•				•			•		
Type of Last Inspection Da				Date of Last Inspection Time S			ection		Airframe Total Time		
						Ho	Hours				
- Emergency Locator Transmitter (	ELT) Information							•			
ELT Installed?/Type		E	ELT Operated? ELT Aided in Locating Accident Site?								
Owner/Operator Information											
Registered Aircraft Owner			Street A	ddress							
Unknown	City		State	Zip Code							
		Street Address									
Operator of Aircraft											
Yeman Flight Academy	City Mukalla							Zip Code			
Operator Does Business As:	Operator Designator Code:										
- Type of U.S. Certificate(s) Held:	None										
Air Carrier Operating Certificate(s)	:										
Operating Certificate: Operator Certificate:											
Regulation Flight Conducted Under: Non-U.S., Non-Commercial											
Type of Flight Operation Conducted	d: Unknown										
		FACTUA	L REPO	RT - AVIATION						Page 2	

## National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: ERA09WA291

Occurrence Date: 05/10/2009

AVIATION				Occurrence Type: Accident					1					
First Pilot Information														
Name						City					Stat	te [	Date of Birth	Age
On File														
Sex: M	Seat Occupied:	: <u>Unknown</u>	Oc	cupational Pil	lot? Unkno	wn				Cer	tificat	e Numbe	er: On File	
Certificate(s):														
Airplane Rating(s):														
Rotorcraft/0	Glider/LTA:													
Instrument	Rating(s):													
Instructor Rating(s):														
Current Bie	ennial Flight Revie	∍w?												
Medical Ce	rt.:	Medic	al Cert. Statu	s:					Da	ate of La	ast Me	edical Ex	cam:	
- Flight Tim	Flight Time Matrix		This Make and Model	Airplane Airplane Single Engine Mult-Engine		Night Actual		Instrument Simulated			Rotorcraft	Glider	Lighter Than Air	
Total Time		<del>                                     </del>	ļ'	<b></b>		↓			$\dashv$		+			
	mmand(PIC)	<del> </del>	ļ	<b></b>	<u> </u>	┼			+		+			<u> </u>
Instructor	D	<del> </del>	ļ	<del> </del>	<del>                                     </del>	+			+		+		+	
Instruction F		<del> </del>	<del>                                     </del>	<del> </del>	<del> </del>	+-			+		+			<u> </u>
Last 90 Day Last 30 Day				+		+		+	+					
Last 24 Hou			<del>                                     </del>						$\dashv$		$\top$		+	
Seatbelt Us	sed? Unknown	Shoi	ulder Harness	Used? Unk	nown		Toxico	ology Per	erformed? Second Pilot? Yes					
Flight Pla	an/Itinerary													
Type of Flig	ght Plan Filed: Ur	nknown												
Departure F	Point						State	1	Airport	port Identifier Departure Time Zo				
Luxor								ŀ	HELX					
Destination	1						State	,	Airport	dentifie	er			
Port Suda	ns				HSPN									
Type of Cle	earance: Unkno	wn												
Type of Airs	space:													
Weather	Information													
Source of V	Wx Information:													
	Unknown													
	,	'		FACTUAI	L REPORT -	- AVL	ATION	1						Page 3

## National Transportation Safety Board FACTUAL REPORT

NTSB ID: ERA09WA291

Occurrence Date: 05/10/2009

7 % ( ) ( )			⊢						1				
AVIATION				Occurrence Type: Accident									
Weather	Information												
WOF ID Observation Time Time Zone				OF Elevati	on	WOF Distance From Accid			dent Site		Direction From Accident Site		
				_									
			Ft.	. MSL				NM I		Deg. Mag.			
Sky/Lowes	st Cloud Condition:						Ft. AGI	_	Condition of	of Ligh	jht:		
Lowest Ce	iling:		Ft.	AGL	Visib	Visibility:			SM Altimeter:				
Temperatu	Temperature: °C Dew Point: °C Weather Conditions						itions at Accid	dent S	ite:				
Wind Direc	eed:			Win	d Gusts:								
Visibility (R	RVR): Ft.	Visibility	(RVV)		SM	_							
Precip and	d/or Obscuration:												
Accident	Information												
Aircraft Dar	mage: Destroyed	A	Aircraft Fire: Unknown					Aircraft Exp	olosio	n <b>Unknown</b>			
- Injury Su	mmary Matrix	Fatal	Serious	Mino	or	None	TOTAL						
First Pi	ilot	1					1						
Second	d Pilot	1					1						
Studen	nt Pilot												
Flight Instructor													
Check	Pilot												
Flight E	Engineer												
Cabin A	Cabin Attendants												
Other C	Other Crew												
Passen	Passengers												
- TOTAL A	ABOARD -	2					2						
Other C	Ground												
- GRAND	O TOTAL -	2					2						

National Transportation Safety Board

NTSB ID: ERA09WA291

reactional Transportation Safety Board		4
FACTUAL REPORT	Occurrence Date: 05/10/2009	
AVIATION	Occurrence Type: Accident	7
	71 - Addidon	I .
Administrative Information		
Investigator-In-Charge (IIC) Paul R. Cox		
Paul R. Cox		
Additional Persons Participating in This Accident	/Incident Investigation:	